



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D5068-3
Job Sheet 170728



Part No: D5068-3

Job Qty: 6 ea

Part Name: Rib



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 1/18/18

Job Tracking No:

Due Date: 3/9/18

Created By: Mario Poulin

Type: SOLD

Description:

Note: D5068 REV.A SHEET 5 IPP REV:A 17.08.30 NEW ISSUE DD VERF:DP

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	6 Ea		3/8/18	0.00	0.00	Start Up Large Fab-3		D.M.L B-1-22
100	Large Fab	6 pcs		3/9/18	0.00	0.95	Large Fab 8		D.M.L B-1-22
110	QC	6 pcs		3/9/18	0.00	0.00	QC5		38
120	Packaging	6 pcs		3/9/18	0.00	0.00	Packaging3 Large Fab		D.M.L B-1-22
130	QC21-SA	6 Ea		3/9/18	0.00	0.00	QC21		

Part Op 100 - 1- Cut tube as per dwg D5068 2- Debur and remove identification markings
Descriptions: 120 - LOCATION: WA004

DAS JAN 23 2018
21
9-00

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
M304TS0.500W.049	Square Tubing	12.6600 ft (2.11 ea)	90-Start up Operation	5010115

25.36

DART
AEROSPACE
S034268



Rib

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

poulin.mario

PART NO: D5068-3
Original Serial #: S034268
Revision:
Operation: Start up Operation
Change No:

01/22/18
Job No: 170728

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					